S35

SHARPENING METHOD



- Hold blade at constant angle relative to strop
- Strop both sides of cutting edge in direction shown



Basic Sharpening Method